



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 1, 2009

Reviewed: PMG

Mine Name: Pitchforth Springs/Multicolor Green	Permit Number: S/027/0033
Operator Name: Dale D. Rogers	Inspection Date: 06/30/2009
Inspector(s): Brett Gregory for Tom Munson	Time: 2:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$6,800.

Permit fee: current.

Purpose of Inspection: Routine inspection to photograph and document the site conditions.

Inspection Summary:

- 1) The bond is due for escalation this year. All permit fees have been paid in full.
 - 2) There were several wooden pallets found on site. They need to be removed if not being used.
 - 5) There is some question whether the road disturbance made to the northeast is on BLM or SITLA property?
 - 10) Some of the plants growing within the disturbed area are noted below in the photographs.
- (Photos attached)

Conclusions and Recommendations

The GPS map from my inspection indicates the mine is over five acres of disturbance (~7.10 acres). This puts the operator in a position to choose one of the following alternatives:

- 1.) The operator may reclaim the quarry leaving the current \$6,800 in place to guarantee revegetation success.

- 2.) The operator may submit a Notice of Intention to commence a Large Mining Operation and post an interim bond totaling \$33,200.
- 3.) The operator may reclaim to a small mine status of 5 acres or less, post additional bond (\$17,800 for a total of \$24,600) to bring the bond to current bonding cost estimates for a five acre disturbance.


Inspector's Signature

BG:vs

cc: Dale Rogers

Jerry_mansfield@blm.gov

O:\M027-Millard\S0270033-pitchforksprings\inspections\insp-06302009.doc

A handwritten signature in black ink, appearing to read "Jerry Mansfield", is written over a horizontal line. The signature is stylized with large, flowing loops.



Unused pallets.



Main body of disturbance.



Top view.



Vegetation growth indicates no recent mining activity.



Snakeweed.



Native thistle.



Halogeton.



Sagebrush